

Radon Monitoring Report

GSS PBS PROPERTY DVLPMNT 8PF
 ATTN: MARION BUNTYN
 BLDG 41 DFC, ROOM 240
 DENVER, CO 80225-0546

LANDAUER

Landauer, Inc. 2 Science Road Glenwood, Illinois 60425-1
 Telephone: (800) 528-8327 Facsimile: (708) 755-7048

Acct. No. 0410176

PROGRAM NAME: UT 0039

Detector Number	Detector Type	Starting Date	Ending Date	Field Data / Comments	Exposure pCi/l-days	Avg. Radon Conc. pCi/l
4736885	DRN	01-JUL-08	09-FEB-09	MIDDLE COPY ROOM	63.0 ±6.18	0.3 ±0.03
4736933	DRN	01-AUG-08	09-FEB-09	1ST FLOOR	63.0 ±6.18	0.3 ±0.03
4736949	DRN	01-AUG-08	09-FEB-09	FRONT CUBICLES	66.1 ±6.39	0.3 ±0.03

①
 ②
 ③
 ④
 RESULTS RELATED ONLY TO MONITORS
 AS RECEIVED BY LANDAUER.

Q.C. Release	Process No.	Report Date	Date Received
DRB	A21611	05-MAR-09	10-FEB-09

⑤
 ⑥
 ⑦
 ⑧
 PAGE 1 OF 1