

1. AIRCRAFT SERIAL NUMBER 8023428				2. MODEL UH-60A			3. DATE			4. PAGE 1		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS /	SYS A	DATE 04 Oct 16	NO 22	TIME 15:03	PID WALZ, NICHOL	DATE	TIME	ACFT HRS				
FAULTS/REMARKS UPPER CONSOLE HEATER RHEOSTAT BENT						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 5642		WHEN DISC G	HOW REC G	MAL EFF 2								
DELAY part on shelf repair next major maint.			WUC 13B			TIPIID ,			TI MANHOURS			
STATUS /	SYS A	DATE 30 May 19	NO 2	TIME 12:16	PID Conversion, Ulls	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSTALL ANGLE BRACKETS FOR MR DE-ICE HARNESS PER H-60-19-AMAM-03, MR DE-ICE/CHIP DETECTOR HARNESS CHAFING AND RE-ROUTING, AT THE NEXT MAIN TRANSMISSION REMOVAL.						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 5949.2		WHEN DISC O	HOW REC O	MAL EFF 1								
DELAY hold until phase			WUC 06A			TIPIID ,			TI MANHOURS			
STATUS —	SYS A	DATE 02 Jul 19	NO 2	TIME 11:44	PID DUFFY, JOSHUA	DATE	TIME	ACFT HRS				
FAULTS/REMARKS UPPER SUPPORT ARM, PN (70400-08158-102), SN (UN-READABLE) SHALL BE REPLACED AT ITS REGULAR SCHEDULED RETIREMENT TIME OR WHEN REMOVED FROM THE AIRCRAFT FOR ANY REASON PER H-60-19-AMAM-08						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 5949.2		WHEN DISC X	HOW REC G	MAL EFF 1								
DELAY			WUC 00			TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8023428				2. MODEL UH-60A			3. DATE			4. PAGE 2							
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION											
STATUS —	SYS A	DATE 21 Oct 19	NO 8	TIME 11:19	PID Generated, Cor	DATE	TIME	ACFT HRS									
FAULTS/REMARKS MAIN ROTOR SHAFT NUT PN/SN VERIFICATION AND DE-CONFLICT IT WITH SNRR OFFICE, AND MARK IAW H-60-19-ASAM-06 DUE AT NEXT PMI INSPECTION						ROUNDS			ACTION CODE			WUC					
						ACTION											
ACFT HRS 5983.3						WHEN DISC O	HOW REC G	MAL EFF 1	PID			CAT			HRS		
DELAY						WUC 00			TIPIID ,			TI MANHOURS					
STATUS /	SYS A	DATE 02 Nov 19	NO 4	TIME 14:06	PID Conversion, Ulls	DATE	TIME	ACFT HRS									
FAULTS/REMARKS WORKING RIVETS ON AIRFRAME BY #2 UPPER DOOR TRACK AFT END (MARKED WITH BLACK GREASE PENCIL)						ROUNDS			ACTION CODE			WUC					
						ACTION											
ACFT HRS 5984						WHEN DISC X	HOW REC G	MAL EFF 2	PID			CAT			HRS		
DELAY WO# SM93090002						WUC 02			TIPIID ,			TI MANHOURS					
STATUS —	SYS A	DATE 06 Mar 20	NO 6	TIME 13:21	PID BISHOP, JEFFERY	DATE	TIME	ACFT HRS									
FAULTS/REMARKS COMPLY WITH REQUIREMENTS OF THE ADDENDUM TO H-60-15-SOF-01 AT 7523 AIRCRAFT HOURS.						ROUNDS			ACTION CODE			WUC					
						ACTION											
ACFT HRS 5990.2						WHEN DISC K	HOW REC O	MAL EFF 2	PID			CAT			HRS		
DELAY						WUC 02			TIPIID ,			TI MANHOURS					

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8023428				2. MODEL UH-60A			3. DATE			4. PAGE 3				
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION								
STATUS ⊗		SYS A	DATE 08 Apr 20		NO 6	TIME 12:38		PID CURTIS, ANDRE			ACFT HRS			
DATE		TIME		ACFT HRS		ROUNDS		ACTION CODE		WUC				
FAULTS/REMARKS WHEN FLYING WITH ANVIS AN/AVS-6 SERIES NVGS, OPERATE IAW AWR 1750 R6 DATED 31 MAR 2020						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 5992.3		WHEN DISC O		HOW REC O		MAL EFF 1								
DELAY				WUC 00		TIPIID ,			TI MANHOURS					
STATUS —		SYS A	DATE 16 Jul 20		NO 1	TIME 09:45		PID GATHRIGHT, AN			ACFT HRS			
DATE		TIME		ACFT HRS		ROUNDS		ACTION CODE		WUC				
FAULTS/REMARKS ENGINE #1 CSM SN GEC001066C REQUIRES REPLACEMENT PER H-60-20-ASAM-02 BY 31 DEC 23						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 6012.1		WHEN DISC O		HOW REC G		MAL EFF 1								
DELAY SEE FAULT NARRATIVE				WUC 04A01		TIPIID ,			TI MANHOURS					
STATUS —		SYS A	DATE 16 Jul 20		NO 2	TIME 09:49		PID GATHRIGHT, AN			ACFT HRS			
DATE		TIME		ACFT HRS		ROUNDS		ACTION CODE		WUC				
FAULTS/REMARKS ENGINE #2 CSM SN GEC003777 REQUIRES REPLACEMENT PER H-60-20-ASAM-02 BY 31 DEC 23						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 6012.1		WHEN DISC O		HOW REC G		MAL EFF 1								
DELAY SEE FAULT NARRATIVE				WUC 04A01		TIPIID ,			TI MANHOURS					

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8023428				2. MODEL UH-60A			3. DATE			4. PAGE 4		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS /	SYS A	DATE 04 Oct 20	NO 1	TIME 12:45	PID Mower, Hope	DATE	TIME	ACFT HRS				
FAULTS/REMARKS 'LOANT' displays on transponder						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6032		WHEN DISC G	HOW REC G	MAL EFF 2								
DELAY w/o av02940002			WUC 00			TIPIID ,			TI MANHOURS			
STATUS ⊗	SYS A	DATE 22 Oct 20	NO 1	TIME 14:11	PID Belyeu, Christop	DATE	TIME	ACFT HRS				
FAULTS/REMARKS aircraft restricted from known icing conditions due to l/h and r/h windshield anti-ice in-op						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6035.4		WHEN DISC B	HOW REC K	MAL EFF 4								
DELAY			WUC 00			TIPIID ,			TI MANHOURS			
STATUS /	SYS A	DATE 04 Nov 20	NO 5	TIME 11:51	PID BISHOP, JEFFERY	DATE	TIME	ACFT HRS				
FAULTS/REMARKS fwd soundproofing of main transmission near ICS box has bad nutplate						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6039.6		WHEN DISC K	HOW REC G	MAL EFF 1								
DELAY w/o# uatc 12000066			WUC 02			TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8023428				2. MODEL UH-60A			3. DATE			4. PAGE 5		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS /	SYS A	DATE 12 Nov 20	NO 5	TIME 07:48	PID Belyeu, Christop	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC	
FAULTS/REMARKS PILOT AND COPILOT WINDSHIELD DE-ICE INOP. CENTER WINDSHIELD FUNCTIONS NORMALLY. TROUBLE SHOOTING COMPLETE WINDSHIELDS REQUIRE REPLACEMENT						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6039.6		WHEN DISC L	HOW REC G	MAL EFF 4								
DELAY COMPLETE AT NEXT MAJOR MAINT.			WUC 02A01			TIPIID ,			TI MANHOURS			
STATUS /	SYS A	DATE 15 Nov 20	NO 6	TIME 07:22	PID EISENHAEUER, JE	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC	
FAULTS/REMARKS FWD MOST T/R DRIVE SHAFT COVER HAS 2 SMALL CRACKS ON FRONT LIP.						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6041.6		WHEN DISC X	HOW REC G	MAL EFF 2								
DELAY W/O UATC12000069			WUC 02			TIPIID ,			TI MANHOURS			
STATUS /	SYS A	DATE 15 Nov 20	NO 9	TIME 15:21	PID CHADBOURNE,	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC	
FAULTS/REMARKS Center windshield antice failed, lower half of windshield would warm up, upper half would remain cold.						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6045.6		WHEN DISC G	HOW REC G	MAL EFF 1								
DELAY w/o submitted			WUC 00			TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8023428				2. MODEL UH-60A			3. DATE			4. PAGE 6		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS /	SYS A	DATE 16 Nov 20	NO 2	TIME 06:28	PID EISENHAUER, JE	DATE	TIME	ACFT HRS				
FAULTS/REMARKS main mod outputseal seeping						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6045.6						WHEN DISC X	HOW REC G	MAL EFF 2				
DELAY within limits will continue to monitor						WUC 00			TIPIID ,			TI MANHOURS
STATUS —	SYS A	DATE 10 Dec 20	NO 1	TIME 00:01	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS SAFETY MESSAGE NUMBER: H-60-21-AMAM-01 DESCRIPTION: COMPLY WITH H-60-21-AMAM-01, MAIN LANDING GEAR DRAG BEAM INSPECTION, BY 06 JUL 21.. IS DUE: 06 JUL 2021 CALENDAR						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6060.7						WHEN DISC O	HOW REC O	MAL EFF 1				
DELAY						WUC 00			TIPIID ,			TI MANHOURS
STATUS —	SYS A	DATE 08 Jan 21	NO 2	TIME 20:12	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A401 PMI-2.						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6071.8						WHEN DISC O	HOW REC O	MAL EFF 1				
DELAY						WUC 00			TIPIID ,			TI MANHOURS

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8023428				2. MODEL UH-60A			3. DATE			4. PAGE 7				
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION								
STATUS /	SYS A	DATE 11 Jan 21	NO 7	TIME 13:41	PID Belyeu, Christop	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC			
FAULTS/REMARKS #2 engine hit check within 5 of upper limit. continue to monitor for next 5 flights						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 6075		WHEN DISC X	HOW REC G	MAL EFF 1										
DELAY cleaned "white cable" cannon plugs cor						WUC 00		TIPIID ,		TI MANHOURS				
STATUS /	SYS A	DATE 23 Jan 21	NO 2	TIME 10:53	PID MACOMBER, WI	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC			
FAULTS/REMARKS The Main Glare Shield light knob is detached/ broken.						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 6086.6		WHEN DISC T	HOW REC G	MAL EFF 3										
DELAY						WUC 00		TIPIID ,		TI MANHOURS				
STATUS /	SYS A	DATE 28 Jan 21	NO 2	TIME 11:14	PID LECLAIR, JOSEPH	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC			
FAULTS/REMARKS #1 ENG HIT within 5 of upper limit						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 6094.3		WHEN DISC G	HOW REC G	MAL EFF 2										
DELAY						WUC 00		TIPIID ,		TI MANHOURS				

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8023428				2. MODEL UH-60A			3. DATE			4. PAGE 8		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X		SYS O	DATE 04 Feb 21		NO 1	TIME 00:01		PID Generated, Cor			ACFT HRS	
ROUNDS		ACTION CODE			WUC							
FAULTS/REMARKS INSP O800 LOGBOOK RECON DUE FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8023428 WAS DUE. STATUS UPGRADED TO X ON: 03 FEB 2021 REFERENCE: AASF SOP						ACTION						
ACFT HRS 6098.7		WHEN DISC O		HOW REC O		MAL EFF 1						
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS O		SYS A	DATE 22 Feb 21		NO 1	TIME 10:56		PID CURTIS, ANDRE			ACFT HRS	
ROUNDS		ACTION CODE			WUC							
FAULTS/REMARKS OPERATE IN ACCORDANCE WITH AWR 2120 R3 DATED 27 SEP 2019 (GeTac Computer), AWR 1956 R4 DATED 04 AUG 2020 (APR-39), AWR 1913 R4 DATED 17 JAN 2020 (ACN LOGBOOK), AWR 1823 R9 DATED 22 NOV 2019 (IVHMS BLOCK 5.0/5C), AWR 1800 R9 DATED 18 JUL 2019 (EDM/BFT), AWR 1753 R9 DATED 17 APR 20(128D GPS), AWR 1738 R7 DATED 26 FEB 2021 (APX-118), AWR 1694 R7 DATED 29 JAN 2020 (DSC), AWR 1682 R25 DATED 01 AUG 2019 (701D TDI), AWR 1607 R11 DATED 13 MAR 2020 (LED CDU/PDU), AWR 1566 R7 DATED 05 FEB 2019 (HPH CABLE GUARD), AWR 1516 R14 DATED 19 FEB 2021 (ELT EBC-406HM), AWR 1513 R16 DATED 03 NOV						ACTION						
ACFT HRS 6098.7		WHEN DISC O		HOW REC O		MAL EFF 1						
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS O		SYS A	DATE 22 Feb 21		NO 2	TIME 10:56		PID CURTIS, ANDRE			ACFT HRS	
ROUNDS		ACTION CODE			WUC							
FAULTS/REMARKS OPERATE IAW THE FOLLOWING AWR'S IF APPLICABLE - AWR 1965 R9 DATED 18 MAR 2020 (APPLE IPAD DEVICES), AWR 1930 R16 DATED 11 DEC 2020 (PMI), AWR 1784 R4 DATED 31 JUL 2019 (SHIP BOARD OPS), AWR 1632 R8 DATED 20 JUL 20(ALP LASER POINTER), AWR 1466 R9 DATED 23 AUG 2019 (GARMIN GPS), AWR 1453 R7 DATED 06 JUN 2019 (MCS), AWR 1407 R6 DATED 28 MAY 2020 (DAY HUD), AWR 1309 R13 DATED 30 SEP 2020 (OREGON SEAT CUSHION), AWR 1308 R13 DATED 24 APR 2019 (IRH R5), AWR 1279 R9 DATED 20 MAY 2020 (COCKPIT/CABIN DRS REMOVED), AWR 1270 R13 DATED 31 AUG 2020(EIBF), AWR 1127 R10 DATED 01 SEP 2020						ACTION						
ACFT HRS 6098.7		WHEN DISC O		HOW REC O		MAL EFF 1						
DELAY				WUC 00		TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8023428				2. MODEL UH-60A			3. DATE			4. PAGE 9		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS /	SYS E	DATE 26 Feb 21	NO 1	TIME 09:49	PID MCGRAW, ALEX	DATE	TIME	ACFT HRS				
FAULTS/REMARKS #1 CONVERTER TERMINAL COVER CRACKED						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6098.7		WHEN DISC Y	HOW REC G	MAL EFF 2								
DELAY				WUC 12A07		TIPIID ,			TI MANHOURS			
STATUS ⊗	SYS A	DATE 02 Mar 21	NO 5	TIME 13:15	PID OILER, KENNETH	DATE	TIME	ACFT HRS				
FAULTS/REMARKS AIRCRAFT RESTRICTED FROM CARGO HOOK OPERASTIONS DUE TO REMOVAL OF CARGO SQIP FOR BEST TURN IN						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6098.7		WHEN DISC O	HOW REC G	MAL EFF 3								
DELAY BEST PROGRAM				WUC 16A01		TIPIID ,			TI MANHOURS			
STATUS —	SYS A	DATE 10 Mar 21	NO 1	TIME 00:01	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A580 RETURN SLAB TO AVIM FOR CAPACITY CHECK (EVERY 24 MONTH) FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8023428 IS DUE. STATUS WILL UPGRADE TO X ON: 09 MAY 2021 REFERENCE: TM 11-6140-203-23 P						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6098.7		WHEN DISC O	HOW REC O	MAL EFF 1								
DELAY				WUC 00		TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8023428				2. MODEL UH-60A			3. DATE			4. PAGE 10		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS /	SYS A	DATE 10 Mar 21	NO 3	TIME 08:12	PID Bartlett, Christo	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC	
FAULTS/REMARKS Light on the ICS box (left side) not compatible with NVGS.						ACTION						
												PID
ACFT HRS 6098.7		WHEN DISC K	HOW REC G	MAL EFF 1								
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS /	SYS A	DATE 11 Mar 21	NO 1	TIME 09:18	PID CHADBOURNE,	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC	
FAULTS/REMARKS #1 side Aft heater vent/ louver not installed, on bulk head panel						ACTION						
												PID
ACFT HRS 6098.7		WHEN DISC B	HOW REC G	MAL EFF 1								
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS /	SYS A	DATE 16 Mar 21	NO 2	TIME 16:15	PID DUFFY, JOSHUA	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC	
FAULTS/REMARKS MACHINE GUN MOUNT GUN ARM (M240) L/H AND R/H RMVD FROM A/C AT 48 LBS MOMENT 13.44 CHART C ENTRY NOT COMPLETED, MUST BE COMPLETED N/L/T 5 JUNE 2021						ACTION						
												PID
ACFT HRS 6099.2		WHEN DISC X	HOW REC G	MAL EFF 1								
DELAY				WUC 00		TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8023428				2. MODEL UH-60A			3. DATE			4. PAGE 11		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS —		SYS A	DATE 01 Apr 21		NO 1	TIME 07:34		PID Generated, Cor		ACFT HRS		
										WUC		
FAULTS/REMARKS SAFETY MESSAGE NUMBER: H-60-21-AMAM-03 DESCRIPTION: COMPLY WITH H-60-21-AMAM-03, AUXILIARY POWER UNIT GENERATOR DA FORM 2410 TRACKING, BY 31 MAY 2021. IS DUE: 31 MAY 2021 CALENDAR						ACTION						
ACFT HRS 6099,2		WHEN DISC O		HOW REC O		MAL EFF 1						
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS —		SYS E	DATE 11 Apr 21		NO 1	TIME 00:00		PID Generated, Com		ACFT HRS		
										WUC		
FAULTS/REMARKS INSP E125 KY-58 PMCS/OPNL CHECK FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8023428 IS DUE. STATUS WILL UPGRADE TO X ON: 29 APR 2021 REFERENCE: TM 11-5810-262-23						ACTION						
ACFT HRS 6099,2		WHEN DISC O		HOW REC O		MAL EFF 1						
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS X		SYS E	DATE 13 Apr 21		NO 1	TIME 16:09		PID COUTURE, ERIC		ACFT HRS		
										WUC		
FAULTS/REMARKS VHF radio inop						ACTION						
ACFT HRS 6109,4		WHEN DISC B		HOW REC B		MAL EFF 4						
DELAY				WUC 19		TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8023428				2. MODEL UH-60A			3. DATE			4. PAGE 12				
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION								
STATUS X	SYS A	DATE 16 Apr 21	NO 1	TIME 00:00	PID Generated, Cor	DATE	TIME	ACFT HRS						
FAULTS/REMARKS INSP A808 APU EVENTS/HRS READINGS DUE FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8023428 WAS DUE. STATUS UPGRADED TO X ON: 15 APR 2021 REFERENCE: TM 1-1520-237-23						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 6109.4						WHEN DISC O	HOW REC O	MAL EFF 1						
DELAY						WUC 00			TI MANHOURS					
STATUS X	SYS A	DATE 19 Apr 21	NO 1	TIME 00:00	PID Generated, Com	DATE	TIME	ACFT HRS						
FAULTS/REMARKS INSP A100 LH/RH ENGINE HISTORY RECORDER READINGS DUE FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8023428 WAS DUE. STATUS UPGRADED TO X ON: 18 APR 2021 REFERENCE: DA PAM 738-751						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 6109.4						WHEN DISC O	HOW REC O	MAL EFF 1						
DELAY						WUC 00			TI MANHOURS					
STATUS —	SYS O	DATE 19 Apr 21	NO 1	TIME 00:00	PID Generated, Com	DATE	TIME	ACFT HRS						
FAULTS/REMARKS INSP O801 128D DAFIF AND WAYPOINT UPDATE REQUIRED FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8023428 IS DUE. STATUS WILL UPGRADE TO X ON: 25 APR 2021 REFERENCE: AASF SOP						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 6109.4						WHEN DISC O	HOW REC O	MAL EFF 1						
DELAY						WUC 00			TI MANHOURS					

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8023428				2. MODEL UH-60A			3. DATE			4. PAGE 13		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 19 Apr 21	NO 2	TIME 12:14	PID BROWN, MICH	DATE	TIME	ACFT HRS				
FAULTS/REMARKS AIRCRAFT INDUCTED INTO BEST PROGRAM ON 19 APRIL 2021, NO SCHEDULED MAINTENANCE PERFORMED AFTER THIS DATE.						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 6109.4			WHEN DISC E	HOW REC G	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 02		TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 19 Apr 21	NO 3	TIME 12:16	PID BROWN, MICH	DATE	TIME	ACFT HRS				
FAULTS/REMARKS REMARK/NOTICE TO BUYER: PRIOR TO DELIVERY OF THE AIRCRAFT TO THE BUYER THE FOLLOWING ITEMS WILL BE REMOVED FROM THE AIRCRAFT AT THE DIRECTION OF THE US GOVERNMENT; TO INCLUDE BUT NOT LIMITED TO: CMWS JUNCTION BOX; SA-26669/ALE-47 (V) CMWS SEQUENCER; SENSOR ELECTRO-OPTIC MISSILE CM-SU-202/AAR-57 (V); DIGITAL COCKPIT DISPLAY UNIT (CMWS); SAFE/ARM CONTROL PANEL (CMWS); CMWS RELAY BOX; MEMORY CARD PMCIA (UDM) MU-1126/AAR-57(V) (CMWS); RECEIVER/TRANSMITTER, RT-1477/ARC-201; CONTROL, C-11466A/ARC-201; KY-58(3EA); KY-58 CONTROL HEAD (3EA); KY-100 AIRTERM; ARC-220/						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 6109.4			WHEN DISC E	HOW REC G	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 02		TIPIID ,			TI MANHOURS			
STATUS —	SYS A	DATE 20 Apr 21	NO 2	TIME 00:01	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A502 INSPECT AND TEST GROUND RECEPTACLE IAW TM 1-1500-204-23 FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8023428 IS DUE. STATUS WILL UPGRADE TO X ON: 26 MAY 2021 REFERENCE: TM 1-1520-237-23P						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 6109.4			WHEN DISC O	HOW REC O	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 00		TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8023428				2. MODEL UH-60A			3. DATE			4. PAGE 14																		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION																						
STATUS —		SYS A	DATE 21 Apr 21	NO 1	TIME 13:25	PID BROWN, MICH		DATE		TIME		ACFT HRS																
								ROUNDS		ACTION CODE		WUC																
FAULTS/REMARKS DURING THE BEST PROGRAM INDUCTION PROCESS, THE FOLLOWING COMPONENTS WERE UNABLE TO HAVE THE S/N'S VERIFIED. ALL OF THESE COMPONENTS HAVE BEEN S/N MATCHED AGAINST MCDS AND THE RECORDS MATCH BETWEEN ACN AND MCDS. THESE COMPONENTS REQUIRE S/N VERIFICATION AT THE NEXT MAJOR MAINT EVENT: SHAFT ASSY, T/R DRIVE SECTION 2, P/N: 70361-03009-047, S/N: A270-02412						ACTION						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS								
ACFT HRS 6109.4		WHEN DISC E		HOW REC G		MAL EFF 1																						
DELAY				WUC 06H08				TIPIID ,			TI MANHOURS																	
STATUS X		SYS A	DATE 22 Apr 21	NO 1	TIME 00:00	PID Generated, Com		DATE		TIME		ACFT HRS																
								ROUNDS		ACTION CODE		WUC																
FAULTS/REMARKS INSP A022 14 DAY FLYABLE STORAGE ENGINE RUN UP FOR HCPTTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8023428 WAS DUE. STATUS UPGRADED TO X ON: 21 APR 2021 REFERENCE: TM 1-1520-237-23P						ACTION						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS								
ACFT HRS 6109.4		WHEN DISC O		HOW REC O		MAL EFF 1																						
DELAY				WUC 00				TIPIID ,			TI MANHOURS																	
STATUS X		SYS A	DATE 23 Apr 21	NO 1	TIME 13:36	PID JUSTUS, NATHA		DATE		TIME		ACFT HRS																
								ROUNDS		ACTION CODE		WUC																
FAULTS/REMARKS AIRCRAFT DEPANELED FOR INDUCTION INTO BEST PROGRAM PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P, BEST SOW AND SES GOP AS A REFERENCE.						ACTION						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS								
ACFT HRS 6109.4		WHEN DISC E		HOW REC G		MAL EFF 1																						
DELAY				WUC 00				TIPIID ,			TI MANHOURS																	

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8023428				2. MODEL UH-60A			3. DATE			4. PAGE 15		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 23 Apr 21	NO 2	TIME 13:37	PID JUSTUS, NATHA	DATE	TIME	ACFT HRS				
FAULTS/REMARKS REMOVED TAIL ROTOR PADDLES PER CUSTOMER REQUEST FOR INDUCTION INTO BEST PROGRAM. USED TM 1-1520-237-23&P WP 0815, SES GOP AND BEST SOW.						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6109.4		WHEN DISC B	HOW REC G	MAL EFF 1								
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 23 Apr 21	NO 3	TIME 13:45	PID JUSTUS, NATHA	DATE	TIME	ACFT HRS				
FAULTS/REMARKS REMOVED STABILATOR FOR INDUCTION INTO BEST STORAGE PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 0539 AS A REFERENCE.						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6109.4		WHEN DISC B	HOW REC G	MAL EFF 1								
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 23 Apr 21	NO 4	TIME 13:49	PID JUSTUS, NATHA	DATE	TIME	ACFT HRS				
FAULTS/REMARKS MAIN ROTOR BLADES REMOVED FOR BEST STORAGE PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 0790 AS A REFERENCE.						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6109.4		WHEN DISC B	HOW REC G	MAL EFF 1								
DELAY				WUC 00		TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8023428				2. MODEL UH-60A			3. DATE			4. PAGE 16		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 23 Apr 21	NO 5	TIME 13:53	PID JUSTUS, NATHA	DATE	TIME	ACFT HRS				
FAULTS/REMARKS Removed CMWS relay box SN: 0945 per customer request IAW TM 1-1520-237-23&P WP 1947.						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 6109.4			WHEN DISC B	HOW REC G	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 23 Apr 21	NO 6	TIME 13:55	PID JUSTUS, NATHA	DATE	TIME	ACFT HRS				
FAULTS/REMARKS Removed APX-118 SN: 0677 per customer request IAW TM 1-1520-237-23&P WP 4442.						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 6109.4			WHEN DISC B	HOW REC G	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 23 Apr 21	NO 7	TIME 13:56	PID JUSTUS, NATHA	DATE	TIME	ACFT HRS				
FAULTS/REMARKS Removed doppler antenna SN: 20188 per customer request IAW TM 1-1520-237-23&P WP 4181.						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 6109.4			WHEN DISC B	HOW REC G	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 00		TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. STATUS X	2. SERIAL NUMBER 8023428	3. SYSTEM CODE A	4. TIME 13:37		
5. FAULT DATE 23 Apr 21		6. FAULT NUMBER 2			
7. FAULT REMOVED TAIL ROTOR PADDLES PER CUSTOMER REQUEST FOR INDUCTION INTO BEST PROGRAM. USED TM 1-1520-237-23&P WP 0815, SES GOP AND BEST SOW.					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
X	All work to be completed IAW TM 1-1520-237-23&P WP 0815, BEST SOW, and SES GOP.				
X	Removed cotter pins (4 each) from PC rods at tail rotor blades.				
X	Removed safety from pitch beam retaining nut hardware.				
X	Removed pitch beam hardware (2 each).				
X	Removed pitch beam nut.				
X	Removed hardware from PC link at tail rotor blade (4 each).				
X	Removed pitch beam.				
X	Removed hardware securing retention plates (12 each).				
X	Removed outboard retention plate.				
X	Removed tail rotor blades (2 each). SN: A009-08629; A009-08879				
X	FOD check required.				
X	Toolbox inventory required.				

DA FORM 2408-13-2-SG, OCT 97
 DA FORM 2408-13-2, NOV 91, MAY BE USED

RELATED MAINTENANCE ACTIONS RECORD
 For use of this form see DA PAM 738-751, the proponent agency is DCSLOG

1. STATUS X	2. SERIAL NUMBER 8023428	3. SYSTEM CODE A	4. TIME 13:45		
5. FAULT DATE 23 Apr 21		6. FAULT NUMBER 3			
7. FAULT REMOVED STABILATOR FOR INDUCTION INTO BEST STORAGE PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 0539 AS A REFERENCE.					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
X	All work to be completed IAW TM 1-1520-237-23&P WP 0539, BEST SOW, and SES GOP.				
X	Removed cotter pins from stabilator attachment hardware (4 each).				
X	Removed limit switch hardware.				
X	Removed lower stabilator actuator hardware.				
X	Removed stabilator hinge hardware (2 each).				
X	Removed stabilator.				
X	FOD check required.				
X	Toolbox inventory required.				

DA FORM 2408-13-2-SG, OCT 97
 DA FORM 2408-13-2, NOV 91, MAY BE USED

RELATED MAINTENANCE ACTIONS RECORD
 For use of this form see DA PAM 738-751, the proponent agency is DCSLOG

1. STATUS ×	2. SERIAL NUMBER 8023428	3. SYSTEM CODE A	4. TIME 13:49		
	5. FAULT DATE 23 Apr 21	6. FAULT NUMBER 4			
7. FAULT MAIN ROTOR BLADES REMOVED FOR BEST STORAGE PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 0790 AS A REFERENCE.					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
×	Removed cotter pins (8 each) from blade pins.				
×	All work to be completed IAW TM 1-1520-237-23&P WP 0790, BEST SOW, and SES GOP.				
×	Disconnected anti-flap springs (4 each).				
×	Disconnected deice electrical connectors (4 each).				
×	Removed blade pins (4 each).				
×	Removed main rotor blades (4 each). SN: A007-00862; A007-01692; A007-13255; A007-07578				
×	FOD check required.				
×	Toolbox inventory required.				

DA FORM 2408-13-2-SG, OCT 97
 DA FORM 2408-13-2, NOV 91, MAY BE USED

RELATED MAINTENANCE ACTIONS RECORD
 For use of this form see DA PAM 738-751, the proponent agency is DCSLOG